

OTHER - AUTRE		REMARKS REMARQUES	SIGNATURE
8.	AIRWORTHINESS CERTIFICATION OR DEFECTS CERTIFICATION DE NAVIGABILITE OU DEFECTUOSITES		9. PILOT OR AME/AMO/A&P + LICENCE NUMBER PILOTE, MECHANICIEN/COMPAGNIE APPROUVEE + No DE LICENCE



17 Airport Road Box 289 Sioux Lookout, ON P8T 1A3
 Ph. Office: (807) 737-0039
 Fax: (807) 737-0040
 parts@skycare.ca
 A.M.O. : 43-06

Aircraft registration: SHOP
 Work report number: SHOP-0734
 Date: Oct 17, 2019
 Journey log

Aircraft TTA# : 0-00 212090-1
 Landing : 0.0

Item	Description	Correction
1	Complete Annual inspection on Cree West PA31-350 C-GCTH as per Piper MM section 3-3 as requested by Cree West PO# Ron-CW-CTH. Annual via email from Ron Basaraba Aug 15, 2019.	Annual inspection on Cree West PA31-350 C-GCTH Completed check serviceable
2	ELT Recertification	ELT Recert installed and tested in aircraft check serviceable
3	Cockpit Fire extinguisher Inspection	Cockpit Fire extinguisher Inspected
4	Replace CO detector	installed New CO Detector check serviceable
5	Compass swing	FOR= 0 30 60 90 120 150 180 210 240 270 300 330 STEER= 360 28 60 90 120 148 178 210 240 272 302 332 Compass card installed in aircraft Dated Oct 17/2019
6	First aid kit Inspection.	First aid kit Inspected No Faults Found
7	Survival kit Inspection.	Survival kit Inspected No Faults Found
8	LH and RH Tachometer calibration check.	LH and RH Tachometer calibration check completed No faults found check serviceable
9	LH low boost pump U/S	LH low boost pump Pump removed S/N # FS 28- 004 Installed S/N # 2F-359 Run pump check for leaks no leaks found but found Breaker would not stay in Curcuit breaker needs replacement replaced curcuit breaker check serviceable
10	LH OB mag switch improperly installed	LH OB mag switch installed Corretly check serviceable
11	LH prop outer deice boots U/S	LH prop outer deice boots U/S Replaced Two De-ice boots on left prop check serviceable
12	#6 cylinder on LH engine low compression 25/80.	Cylinder Removed Cylinder installed run look for leaks no leaks found check serviceable
13	RH turbo mount cracked	RH turbo mount cracked removed installed Overhauled mount safty all bolts run engine check for leaks lines that were removed check serviceable
14	LH turbo mount cracked	L/H turbo mount cracked removed installed Overhauled mount safty all bolts run engine check for leaks lines that were removed check serviceable
15	Fuel cap orings weathered.	Fuel cap orings replaced with New O-rings check serviceable
16	R/H prop outer deice boots U/S	R/H prop outer deice boots U/S Replaced Two De-ice boots on left prop check serviceable
17	R/H EGT Probe U/S	R/H EGT Probe Replaced with New check serviceable
18	AFT Heater 100 hour	AFT 100 hour completed as per IAW C & D MM tested heater No faults found CHECK SERVICEABLE
19	FWD Heater 1000/500/100 hr	FWD Heater 1000/500/100 hr completed as per IAW Janitrol MM tested heater No faults found CHECK SERVICEABLE
20	Panel lights U/S	Found Breaker to be U/S removed breaker and replaced with new check serviceable
21	L/H Oil and filter screen Change	L/H Oil and filter screen Changed with 20w50 Phillips oil New Filter And Lock wirer filter and cleaned Suction screen and lock wirer and installed new crush Gasket run engine check for leaks No leaks found check serviceable
22	R/H Oil and filter screen Change	R/H Oil and filter screen Changed with 20w50 Phillips oil New Filter And Lock wirer filter and cleaned Suction screen and lock wirer and installed new crush Gasket run engine check for leaks No leaks found check serviceable

The maintenance described above has been performed in accordance with the applicable standards of airworthiness.

Name: Gordon Humphrey Authorization #: ACA #12

Name: Don Stever License no: ACA #17



Next Maintenance: Prochain Entretien:	Due:	Due:	Due:	Due:
--	------	------	------	------

REMARKS REMARQUES		SIGNATURE
OTHER - AUTRE	8. AIRWORTHINESS CERTIFICATION OR DEFECTS CERTIFICATION DE NAVIGABILITE OU DEFECTUOSITES	9. PILOT OR A&P / LICENCE NUMBER PILOTE, MECHANICIEN/COMPAGNIE APPROUVEE + No DE LICENCE



Northern Airborne Maintenance
193 Airport Rd
Sioux Lookout, ON P8T 1B3
Ph. Office: 807-737-4596
Fax: 807-737-4596
northernairbornemaint@yahoo.ca
A.M.O. : AMO 47-02

Aircraft registration: C-GCTH
Work report number: 18144NAM
Date: Jul 16, 2018
Journey log

Aircraft TTAF : 12090.1
Landing : 0.0

Item	Description	Correction
1	PO#GCTH2018-047	
2	reinstall LH / RH props (removed for C-GBDN)	LH / RH props reinstalled w/ new orings. ground run / leak check completed w/ no faults. RH prop s/n: DJ10515A TSO: 1732.1, LH prop s/n: DJ10431A TSO: 2276.5
3	reinstall LH / RH pitot tubes (removed for C-GBDN) perform leak check	LH / RH pitot tubes reinstalled. leak check completed w/ no faults found.

The maintenance described above has been performed in accordance with the applicable standards of airworthiness.

Name: Will Busch License no.: ACA#2 NAM



17 Airport Road Box 289 Sioux Lookout, ON P8T 1A3
Ph. Office: (807) 737-0039
Fax: (807) 737-0040
parts@skycare.ca
A.M.O. : 43-06

Aircraft registration: SHOP
Work report number: SHOP-0638
Date: May 16, 2019
Journey log

Aircraft TTAF : 12090.10
Landing : 0.0

Item	Description	Correction
1	AD2003-24-07 Rudder Tube Corrosion Inspection On PA31-350 C-GCTH as per Cree west PO# CW-Ron.	Tail cone removed. Rudder Tube corrosion insp completed IAW AD 2003-24-07, corrosion X applied to torque tube. Tail cone reinstalled. No fault found at this time.
2	AD2013-10-04 Exhaust Inspection LH and RH engines on PA31-350 C-GCTH as per Cree west PO# CW-Ron.	Cowls removed from LH and RH engines. Exhaust insp on LH and RH engines completed IAW AD2013-10-04, Cowls reinstalled. No faults at this time.

The maintenance described above has been performed in accordance with the applicable standards of airworthiness.

Name: Richard Parsons Authorization #: ACA #30




Next Maintenance: Prochain Entretien:	Due: <u>900 hr mgs</u> <u>12123.9</u>	Due: <u>CPS nav clater</u> <u>July 19/18</u>	Due: <u>2009-13-06(F)</u> <u>Part 1, 11</u> <u>12119.4</u>	Due:
--	--	---	--	------

TIME - FICHE DE TEMPS

[illegible]

page. When the maintenance time is reached, the due time in the next available space.

la page droite. Quand le temps d'entretien

OTHER - AUTRE		REMARKS REMARQUES	SIGNATURE
8.		AIRWORTHINESS CERTIFICATION OR DEFECTS CERTIFICATION DE NAVIGABILITE OU DEFECTUOSITES	9. PILOT OR A/ME/JAN/ASP + LICENCE NUMBER PILOTE, MECHANICIEN/COMPAGNIE APPROUVEE + No DE LICENCE
 Northern Airborne Maintenance 193 Airport Rd Sioux Lookout, ON P8T 1B3 Ph. Office: 807-737-4596 Fax: 807-737-4596 northernairbornemaint@yahoo.ca A.M.O. : AMO 47-02 Aircraft TTAF : 12083.4 Landing : 0.0		Aircraft registration: C-GCTH Work report number: 18137NAM Date: Jul 04, 2018 Journey log	
Item	Description	Correction	
1	PO#GCTH2018-045		
2	RH tach jumpy	RH tach drive cables inspected and lubricated. transmission on firewall lubricated. ground run completed w/ no further faults found	
3	RH fuel flow indication low	Fuel flow gauge replaced. s/n on: 154300. ground run / leak check completed w/ no further faults found	
The maintenance described above has been performed in accordance with the applicable standards of airworthiness.			
Name:  Will Busch		License no.: ACA#2 NAM	
		April CA 836821	
		April CA 836821	
		April CA 836821	
		April CA 836821	
Preflight inspection completed (AW elementary Maint.		 April CA 836821	
Preflight inspection completed FAW elementary Maint: added 1st oil Rhensie		April CA 836821	
 Northern Airborne Maintenance 193 Airport Rd Sioux Lookout, ON P8T 1B3 Ph. Office: 807-737-4596 Fax: 807-737-4596 northernairbornemaint@yahoo.ca A.M.O. : AMO 47-02 Aircraft TTAF : 12090.1 Landing : 0.0		Aircraft registration: C-GCTH Work report number: 18142NAM Date: Jul 16, 2018 Journey log	
Item	Description	Correction	
1	PO#GCTH2018-046		
2	remove LH / RH props for C-GBDN	LH and RH props removed from A/C for use on C-GBDN. LH prop s/n: DJ10431A TSO: 2276.5. RH prop s/n: DJ10515A TSO: 1732.1	
3	remove LH / RH pitot tubes for C-GBDN	LH and RH pitot tubes removed from A/C for use on C-GBDN	
The maintenance described above has been performed in accordance with the applicable standards of airworthiness.			
Name:  Will Busch		License no.: ACA#2 NAM	

Next Maintenance: Prochein Entretien:	Due: 900hr msd 12119.4 12123.9	Due: GPS new data July 19/18	Due: 2009-13-06 (FRI) 3, 11 12119.4	Due:
--	--------------------------------------	---------------------------------	---	------

REMARKS
REMARKS

SIGNATURE

[illegible]

of the right-hand page. When the maintenance time is reached, the **Next Maintenance** due time in the next available space.

à l'adresse du bas de la page droite. Quand le temps d'entretien



Aircraft TTAf : 12073.1
Landing : 0.0

Aircraft registration: C-GCTH
Work report number: 18132NAM
Date: Jun 26, 2018
Journey log

HSI head until s/n: 5040 removed and replaced w/ repaired head unit s/n: 3313. ground checked w/ no faults. defect cleared

The maintenance described above has been performed in accordance with the applicable standards of airworthiness.

Name: Will Busch License no.: ACA#2 NAM

Config Change D NSAS ELEMENTARY WORK

Pre-flight inspection Completed (AW elementary Maint

6 seat removed 1Aw elementary maint.

CA443411

22 → CA 443411

Handwritten signature

Arif CA 836821

Am CA 836821

CA443411

Ad # 836821

CA44341

April CH 836821

CA44341

Hand CA 83682

CA443411

April CA 836821

ABC

Aircraft registration: C-GCTH
Work report number: 18136NAM
Date: Jul 04, 2018
Journey log

Northern Airborne Maintenance
193 Airport Rd
Sioux Lookout, ON P8T 1B3
Ph. Office: 807-737-4596
Fax: 807-737-4596
northernairbornemaint@yahoo.ca
A.M.O. : AMO 47-02

Aircraft TTAF : 12083.4
Landing : 0.0

Item	Description
1	PO#GCTH2018-044
2	LH engine EGT indication erratic, replace probe

The maintenance described above has been performed in accordance with the applicable standards of airworthiness.

Name: Will Busch License no.: ACA#2 NAM

Correction

LH engine EGT probe replaced. ground run up completed w/ no further faults found

Next Maintenance:
Prochain Entretien:

Due: 700 hr
12119.4

Due: GHS new date
July 19/18

Due™

	Due
--	-----

OTHER - AUTRE	OTHER - AUTRE	REMARKS REMARQUES	SIGNATURE
	8.	AIRWORTHINESS CERTIFICATION OR DEFECTS CERTIFICATION DE NAVIGABILITE OU DEFECTUOSITES	9. PILOT OR A.M.O. / PILOTE + LICENCE NUMBER PILOTE, MECHANICIEN/COMPAGNIE APPROUVEE + No DE LICENCE
		Reflight insp completed IAW elementary maint. 2 qts oil added to LH engine.	<i>[Signature]</i> CA443411
		Reflight insp completed IAW elementary maint.	<i>[Signature]</i> CA443411
			<i>[Signature]</i> CA443411



Northern Airborne Maintenance
193 Airport Rd
Sioux Lookout, ON P8T 1B3
Ph. Office: 807-737-4596
Fax: 307-737-4596
northernairbornemaint@yahoo.ca
A.M.O. : AMO 47-02

Aircraft registration: C-GCTH
Work report number: 18109NAM
Date: May 30, 2018
Journey log

Aircraft TTAF : 12019.4
Landing : 0.0

Item	Description	Correction
1	PO#GCTH:2018-035	
2	8th 100 Hour Inspection Accomplishment	8th 100 hour inspection completed IAW NSAS MSA
3	2009-13-06 Part (F) Part (2) I,II Nose Baggage Door Lock (Inspection/Lube) Accomplishment	inspection completed IAW 2009-13-06 part(f) part(2) I,II w/ no faults found
4	82-27-13R2 "A" (3) Flap Transmission Wear Inspection Accomplishment	inspection completed IAW 82-27-13R2"A"(3) w/ no faults found
5	Special - De-ice Boots Clean de-ice boots apply ICEx/Shinmaster Accomplishment	deice boots cleaned and treated w/ shinmaster
6	Special - Deferred Defects Review deferred defects control sheet, rectify IAW MCM 5.2(f) Accomplishment	deferred defect #7 and #12 remain open @ this time.
7	Special - Heater meter Report Fwd/Aft heater hobbs-X Accomplishment	fwd heater: 1668.6. Aft: 503.6
8	Special - LDG weight LDG weight increase kit-Visual Accomplishment	LDG weight increase kit inspection completed w/ no faults found
9	Special - Wing Rib Wing rib reinforcement-Visual Accomplishment	wing rib reinforcement inspection completed w/ no faults found
10	clean, inspect, leak check fuel filters	fuel filters cleaned / inspected, leak checked serviceable
11	2013-10-04 Engine - Exhaust visual inspection(L/H & R/H engines) Accomplishment	LH / RH engine exhaust inspection completed IAW 2013-10-04 w/ no faults found
12	2015-19-07(e)(1)(ii) Injector Fuel Lines (L/H & R/H Engine) Accomplishment	LH / RH engine injector line inspection completed IAW 2015-19-07(e)(1)(ii) w/ no faults found
13	Special - Filter Engine Induction Air Filter (L/H) - (Replace) Accomplishment	LH engine induction air filter replaced
14	Special - Filter Engine Induction Air Filter (R/H) - (Replace) Accomplishment	RH engine induction air filter replaced
15	Special - Filter Pneumatic pump inlet filters, LH and RH- (Replace) Accomplishment	LH / RH engine pneumatic pump inlet filter replaced
16	Special - Prop spinner L/H & R/H TCB composite spinner/back plate-Visual Accomplishment	LH / RH TCB prop spinner / backplate inspection completed w/ no faults found
17	Special - Tanis Heater Inspect LH and RH engine Tanis heaters Accomplishment	LH / RH engine tanis heater inspection / function check completed w/ no faults found
18	check / replaced LH / RH engine oil filter	LH / RH engine oil filter checked for contamination none found, filter replaced.
19	change LH / RH engine oil	LH / RH engine oil changed, filled w/ 11 qts 20w50
20	service LH / RH prop	LH / RH prop greased @ fittings w/ shell #6, air charge checked @ 40psi
21	check / replace LH / RH engine HYD filter	LH / RH engine HYD filter checked, no contaminants found, filter replaced
22	wash LH / RH engine, check / lube controls	LH / RH engine washed, controls fwd of firewall checked and spray lubed
23	clean, gap, test LH / RH engine spark plugs	LH / RH engine spark plugs cleaned, gapped, tested and reinstalled

The maintenance described above has been performed in accordance with the applicable standards of airworthiness.

Name: *[Signature]* License no.: ACA#2 NAM
Will Busch

Next Maintenance: Prochain Entretien:	Due: 100 hr insp 12023.9	Due: GPS Nav data Jun 21, 2018	Due: 2013-10-04 12062.4	Due:
--	-----------------------------	-----------------------------------	----------------------------	------



Northern Airborne Maintenance
193 Airport Rd
Sioux Lookout, ON P8T 1B3
Ph. Office:807-737-4596
Fax:807-737-4596
northernairbornemaint@yahoo.ca
A.M.O. : AMO 47-02

Aircraft registration: C-GCTH
Work report number: 18105NAM
Date: May 24, 2018
Journey log

Aircraft TTAf : 12008.6
Landing : 0.0

Description

Correction

Item 1 PO#GCTH2018-033
2 replace GPS antenna
The maintenance described above has been performed in accordance with the applicable standards of airworthiness.

GPS antenna replaced. s/n on: 144026. function checked w/ no faults

AK APPROVED FOR DAY AND NIGHT VFR ONLY.

-WB.

License no.: ACA#2 NAM

Name: Will Busch

CA449995

CA443411

CA443411

CA443411



Northern Airborne Maintenance
193 Airport Rd
Sioux Lookout, ON P8T 1B3
Ph. Office:807-737-4596
Fax:807-737-4596
northernairbornemaint@yahoo.ca
A.M.O. : AMO 47-02

Aircraft registration: C-GCTH
Work report number: 18108NAM
Date: May 28, 2018
Journey log

Aircraft TTAf : 12012.4
Landing : 0.0

Description

Correction

Item 1 PO#GCTH2018-034
2 100 Hour Inspection Accomplishment- Inspect AC to the degree necessary to grant a 10hr tolerance IAW NSAS MSA
3 2009-13-06 Part (F) Part (2) I,II Nose Baggage Door Lock (Inspection/Lube) Accomplishment
4 2013-10-04 Engine - Exhaust visual inspection(L/H & R/H engines) Accomplishment
5 2015-19-07(e)(1)(ii) Injector Fuel Lines (L/H & R/H Engine) Accomplishment
6 82-27-13R2 "A" (3) Flap Transmission Wear Inspection Accomplishment
The maintenance described above has been performed in accordance with the applicable standards of airworthiness.

AC inspected to the degree necessary to grant a 10hr tolerance to the next 100hr inspection IAW NSAS MSA. Now due 12033.9hrs
Inspection completed IAW 2009-13-06 Part (F) Part (2) I,II. No faults found.
Inspection completed IAW 2013-10-04. No faults found.
Inspection completed IAW 2015-19-07(e)(1)(ii). No faults found.
Inspection completed IAW 82-27-13R2"A"(3). No faults found.

Name: James Doggett License no.: ACA#3 NAM

Added 1qt of oil each engine

CA443411

CA443411

CA443411

CA443411

CA443411

Next Maintenance:
Prochain Entretien:

Due: 100HR INSPECTION
12023.9 12033.9

Due: 2013-10-04 DATE
12015.6

Due: GPS NAV DATA
@ JUNE 24, 2018

Due: 2013-10-04
12062.4hrs

REMARKS
REMARQUES

SIGNATURE

9.

PILOT OR AME/AMO/ASP + LICENCE NUMBER
PILOTE, MECHANICIEN/COMPAGNIE
APPROUVÉE + NO DE LICENCE

AIRWORTHINESS CERTIFICATION OR DEFECTS

CERTIFICATION DE NAVIGABILITE OU DEFECTUOSITES

8.

OTHER - AUTRE



Northern Airborne Maintenance
193 Airport Rd
Sioux Lookout, ON P8T 1B3
Ph. Office: 807-737-4596
Fax: 807-737-4596
northernairbornemaint@yahoo.ca
A.M.O. : AMO 47-02

Aircraft registration: C-GCTH
Work report number: 18092NAM
Date: May 09, 2018
Journey log

Aircraft TTAF : 11980.2
Landing : 0.0

Correction

Item Description

- 1 PO#GCTH2018-028
- 2 500hr Magneto Insp (L/H engine) (INBD) P/N: 6360 S/N: G-04249 Inspection
- 3 Special - Pneumatic lines FWD firewall/nac (Visual) - L/H & R/H Accomplishment
- 4 98-08-18 Elevator Bungee Spring (Bungee only) Accomplishment

The maintenance described above has been performed in accordance with the applicable standards of airworthiness.

Name: Will Busch

License no.: ACA#2 NAM

Name:

Graham Busch

License no: Insp#1

overhauled magneto installed s/n on: G-04249. timing to engine set @ 20 degrees BTC #1. ground runs completed w/ no faults
LH / RH engine pneumatic line inspection completed w/ no faults found
elevator bungee spring replaced IAW 98-08-18. TTSN: 976.4
I certify that I have conducted a dual safety inspection of the controls affected by the work done.

VB CA601099
VB CA601099

MLBL

shw CA443411
shw CA443411

shw CA4434
shw CA4434

shw CA4434
shw CA4434

shw CA4434
shw CA4434

shw CA4434
shw CA4434

Pre-flight inspection Completed IAW elementary Maint

Pre-flight inspection Completed IAW elementary Maint

Right engine oil leak. oil cap not secure properly

Pre-flight inspection completed IAW elementary Maint

Pre-flight inspection completed IAW elementary Maint

REMARKS
REMARQUES

SIGNATURE

OTHER - AUTRE

8.

AIRWORTHINESS CERTIFICATION OR DEFECTS

CERTIFICATION DE NAVIGABILITE OU DEFECTUOSITES

9.

PILOT OR A/MO/A&P + LICENCE NUMBER
PILOTE, MECHANICIEN/COMPAGNIE
APPROUVEE + No DE LICENCE

Northern Airborne Maintenance
193 Airport Rd
Sioux Lookout, ON P8T 1B3
Ph. Office: 807-737-4596
Fax: 807-737-4596
northernairbornemaint@yahoo.ca
A.M.O. : AMO 47-02

Aircraft registration: C-GCTH
Work report number: 18089NAM
Date: May 04, 2018
Journey log

Aircraft TTAf : 11965.6
Landing : 0.0

Item	Description	Correction
1	PO#GCTH2018-026	
2	050 Hour Inspection Accomplishment	50 hour inspection completed IAW NSAS MSA
3	Special - De-ice Boots Clean de-ice boots apply ICEX/Shinmaster Accomplishment	Deice boots cleaned and treated w/ Ice-x
4	Special - Heater meter Report Fwd/Aft heater hobbs-X Accomplishment	fwd hobbs : 1654.5 Aft: 503.3
5	wash / lube LDG gear	LDG gear washed. controls fwd of firewall checked and spray lubed
6	2013-10-04 Engine - Exhaust visual inspection(L/H & R/H engines) Accomplishment	LH / RH engine exhaust inspection completed IAW 2013-10-04
7	check / replace LH / RH engine oil filter	LH / RH engine oil filter checked for contaminants none found filter replaced
8	change LH / RH engine oil	LH / RH engine oil changed. filled w/ 11 qts 20w50
9	check LH / RH prop air charge	LH / RH prop air charge checked @ 40 psi
10	wash LH / RH engine. check / lube controls	LH / RH engine washed. controls fwd of firewall checked and spray lubed

The maintenance described above has been performed in accordance with the applicable standards of airworthiness.

Name:

Will Busch

License no.: ACA#2 NAM

CA 441342 B
CA 441342

ALBC

VB CA 601099

VB CA 601099

ALBC

VB CA 601099

VB CA 601099

VB CA 601099

VB CA 601099

VB CA 601099

VB CA 601099

VB CA 601099

VB CA 601099

VB CA 601099

VB CA 601099

VB CA 601099

VB CA 601099

Preflight inspection completed IAW elementary maint.
4 seats removed IAW elementary maint.
4 seats reinstalled IAW elementary maint.
Preflight inspection completed IAW elementary maint.

Preflight

OTHER - AUTRE		REMARKS REMARQUES	SIGNATURE
8.		AIRWORTHINESS CERTIFICATION OR DEFECTS CERTIFICATION DE NAVIGABILITE OU DEFECTUOSITES	9. PILOT OR A/ME/AMO/A&P + LICENCE NUMBER PILOTE, MECHANICIEN/COMPAGNE APPROUVEE + No DE LICENCE



Northern Airborne Maintenance
193 Airport Rd
Sioux Lookout, ON P8T 1B3
Ph. Office: 807-737-4596
Fax: 807-737-4596
northernairbornemaint@yahoo.ca
A.M.O. : AMO 47 92

Aircraft registration: C-GCTH
Work report number: 18070NAM
Date: Apr 13, 2018
Journey log

Aircraft TTAF : 11919.0
Landing : 0.0

Item	Description	Correction
1	PO#GCTH2018-021	
2	100 Hour Inspection Accomplishment	77h 100 hour inspection completed IAW NSAS MSA
3	2009-13-06 Part (F) Part (2) I,II Nose Baggage Door Lock (Inspection/Lube) Accomplishment	inspection completed IAW 2009-13-06 Part (F) Part (2) I,II w/ no faults found
4	82-27-13R2 "A" (3) Flap Transmission Wear Inspection Accomplishment	inspection completed IAW 82-27-13R2 "A"(3) w/ no faults found
5	Special - De-ice Boots Clean de-ice boots apply ICEX/Shinemaster Accomplishment	Deice boots cleaned and treated w/ Ice-X
6	Special - Deferred Defects Review: deferred defects control sheet, rectify IAW MCM 5.2(f) Accomplishment	Deferred defects reviewed IAW MCM 5.2(f). item #7 and #12 remain open
7	Special - Heater meter Report Fwd/Aft heater hobbs-X Accomplishment	Fwd heater - 1624.1 Aft heater - 503.1
8	Special - LDG weight LDG weight increase kit-Visual Accomplishment	LDG weight increase kit inspection completed w/ no faults found
9	Special - Wing Rib Wing rib reinforcement-Visual Accomplishment	Wing rib reinforcement inspection completed w/ no faults found
10	Wash / Lube LDG gear	LDG gear washed, greased @ fittings, all switches, hinges and pivot points spray lubed
25	100 hour inspection / PDT due on FWD heater IAW 2004-21-05(f)	100 hr inspection / PDT completed on FWD heater IAW 2004-21-05(f) w/ no faults found
11	2013-10-04 Engine - Exhaust visual inspection(L/H & R/H engines) Accomplishment	LH / RH engine exhaust inspection completed IAW 2013-10-04 w/ no faults found
12	2015-19-07(e)(1)(ii) Injector Fuel Lines (L/H & R/H Engine) Accomplishment	LH / RH engine injector line inspection completed IAW 2015-19-07(e)(1)(ii) w/ no faults found
13	Special - Filter Pneumatic pump inlet filters, LH and RH- (Replace) Accomplishment	LH / RH engine pneumatic pump inlet filter replaced
14	Special - Prop spinner L/H & R/H TCB composite spinner/back plate-Visual Accomplishment	LH / RH TCB prop spinner / backplate inspection completed w/ no faults found
15	Special - Tanis Heater Inspect L/H and RH engine Tanis heaters Accomplishment	LH / RH engine tanis inspection / function check completed w/ no faults found
16	clean, gap, test LH / RH engine spark plugs	LH / RH engine spark plugs cleaned, gapped, tested and reinstalled
17	check / replace LH / RH engine oil filter	LH / RH engine oil filter checked for contaminants, none found, filter replaced
18	change LH / RH engine oil	LH / RH engine oil changed, filled w/ 11 qts 20w50
19	check LH / RH engine mag timing	LH / RH engine mag timing checked @ 20 degrees BTC #1
20	check / replace LH / RH engine HYD filter	LH / RH engine HYD filter checked, no contaminants found, filter replaced
21	service LH / RH prop	LH / RH prop greased @ fittings w/ shell #6, air charge checked @ 40 psi
22	wash LH / RH engine, check / lube controls	LH / RH engine washed, controls fwd of firewall checked and spray lubed
23	LH engine Cyl # 6 exhaust riser worn	LH engine CYL#6 exhaust riser replaced
24	LH turbo, oil found in turbine housing, turbo to be replaced	LH engine turbocharger replaced s/n on: A1024149

The maintenance described above has been performed in accordance with the applicable standards of airworthiness.

Name: W. Busch License no.: ACA#2 NAM

CA 443411 SV
SV CA443411
SV CA443411
SV CA443411

Next Maintenance: Prochain Entretien:	Due: <u>50hr</u> <u>11973.9</u>	Due: <u>GPS no data</u> <u>Apr 26/18</u>	Due: <u>RAI vac pump</u> <u>11972.0</u>	Due: <u>2131004</u> <u>11969.0</u>
--	------------------------------------	---	--	---------------------------------------